

A photograph of a rustic wooden shed with a corrugated metal roof. The shed is surrounded by greenery, including a large bush with red flowers in the background and various plants in the foreground. A stack of firewood is visible inside the shed.[illegible]



1	Tipologia Funzionale	EDIFICIO PREV. RESIDENZIALE	A		BAITA	E	
		ED.MISTO RESIDENZIALE RURALE	B		MALGA	F	
		EDIFICIO RURALE	C		DEPOSITO	G	
		STALLA-FIENILE	D		ACCESSORIO	H	X
2	Epoca di costruzione	ANTERIORE AL 1860	8				
		TRA IL 1860 E IL 1939	6				
		POSTERIORE AL 1939	4			4	
3	Tipologia architettonica storica	ALTA DEFINIZIONE	8				
		MEDIA DEFINIZIONE	6				
		BASSA DEFINIZIONE	4				
		NESSUNA DEFINIZIONE	0			0	
4	Permanenza dei caratteri formali tradizionali	VOLUMETRICI ORIGINALI	2	1	0	0	
		CARATTERI COSTRUTTIVI	2	1	0	0	
		CARATTERI COMPL.	2	1	0	0	
		ASPETTI DECORATIVI	2	1	0	0	
						4	
5	Degrado fisico	NULLO					
		MEDIO					
		ELEVATO				X	
6	Grado di utilizzo	UTILIZZATO				X	
		SOTTOUTILIZZATO					
		IN STATO DI ABBANDONO					
7	Spazi di pertinenza	ALTA QUALITA'					
		MEDIA QUALITA'					
		BASSA QUALITA'				X	
8	Vincoli legislativi						
9	Categoria di intervento prevista nel piano precedente	Demolizione con ricostruzione					
10	Note: finalizzata a ricomposizione volumetrica e formale						

PROGETTO

11	Categoria di intervento prevista	RESTAURO	
		RISANAMENTO CONSERVATIVO	
		RISTRUTTURAZIONE	X
		DEMOLIZIONE	
12	Vincoli particolari:		
13	Categoria di intervento per gli spazi di pertinenza	Inedificabile	
14	Sopraelevazione per il recupero dei sottotetti a fini abitativi, ai sensi dell'art. 105 Legge provinciale 4 agosto 2015, n. 15.	SI	
		NO	X